

**THREE YEAR REINSPECTION  
JULY 1, 1998**

**DESIGNATED PERSON INFORMATION AND REINSPECTION  
APPROVAL**

**Designated Person:**

**Terrance Feravich  
Executive Director of Operations  
GRAND RAPIDS PUBLIC SCHOOLS  
900 Union Street, NE  
Grand Rapids MI 49503**

**Telephone Number: (616) 771-3010**

***This statement certifies that the three year re-inspection has been conducted by accredited persons and in accordance with the AHERA regulations. I have reviewed the revised plan, the recommended response actions and schedules, and approve for implementation.***

**Terrance Feravich  
Executive Director of Operations**

**Date**

*Terrance Feravich*  
*3/12/98*

**THREE YEAR REINSPECTION  
JULY 1, 1998**

**Name of accredited inspectors and Management Planners  
who performed reinspection:**

**Name: Bruce Johnson**

**Signature: Bruce Johnson**

**Name: Ron VanderZand**

**Signature: Ron VanderZand**

**THREE YEAR REINSPECTION  
JULY 1, 1998**

***This reinspection was done in accordance with AHERA Act 763.85, Part B. All known Asbestos Containing and all assumed Asbestos Containing Material listed in the Management Plan was visually inspected to determine if there has been a change in the condition of the material from an undamaged state, to one showing damage.***

***In addition to inspecting the Asbestos Containing Building Material, (ACBM) listed in the Management Plan, we looked for ACBM that may have been overlooked in the original inspection. If any were found it was added to the Management Plan with assessments and recommendations.***

***The visual inspection was performed by Bruce Johnson and Ron VanderZand on the entire building with the use of the Management Plan, along with the 1992 & 1995 reinspection and all of the 6 months surveillances, to determine if there has been changes in the physical condition of any ACBM, and to assure that all past response actions and schedules were met.***

***For quick reference, the ASBESTOS LOCATIONS section gives an updated list of all known or assumed ACBM locations found in this building. However, there may be ACBM located behind walls, above ceilings, or in areas that are not accessible. If ACBM is present in these areas, the condition of it is unknown and this should be a consideration before any remodeling or demolition is started.***

***Since the inside of this building has no friable ACBM no assessment is necessary and we recommend all non-friable material be maintained under an operation and maintenance program.***