

THREE YEAR REINSPECTION

JULY 1, 1995

**DESIGNATED PERSON INFORMATION AND REINSPECTION
APPROVAL**

Designated Person:


James P. Sneathen
Executive Director of Operations
GRAND RAPIDS PUBLIC SCHOOLS
900 Union Street, NE
Grand Rapids, MI 49503

Telephone Number: (616) 771-3010

School Name and Address:

North Park Elementary
3375 Cheney, NE

This statement certifies that the three year re-inspection has been conducted by accredited persons and in accordance with the AHERA regulations. I have reviewed the revised plan, the recommended response actions and schedules, and approve for implementation.


James P. Sneathen
Executive Director of Operations

May 31, 1995
Date

THREE YEAR REINSPECTION
JULY 1, 1995

State of Michigan accreditation information for inspector and Management Planner

Name of accredited inspectors and Management Planners who performed reinspection:

Name: Bruce Johnson Accrd. No. .

Signature: Bruce Johnson

Name: Ron VanderZand Accrd. No. .

Signature: Ron VanderZand

Name: Bob Langerak Accrd. No. .

Signature: Bob Langerak

THREE YEAR REINSPECTION JULY 1, 1995

This reinspection was done in accordance with AHERA Act 763.85, Part B. All known asbestos containing and all assumed Asbestos Containing Material listed in the Management Plan was visually inspected to determine if there has been a change in the condition of the material from an undamaged state, to one showing damage.

In addition to inspecting the Asbestos Containing Building Material, (ACBM) listed in the Management Plan, we looked for ACBM that may have been overlooked in the original inspection and the 1992 reinspection. If any were found it was added to the Management Plan with assessments and recommendations.

Along with the reinspection we added a new section ASBESTOS LOCATIONS to the Management Plan. This section gives an updated list of all known or assumed ACM locations found in this building.

The visual inspection was performed by, Bruce Johnson and Ron VanderZand on the entire building with the use of the Management Plan, along with the 1992 reinspection and all of the 6 months surveillances, to determine if there has been changes in the physical condition of any ACBM, and to assure that all past response actions and schedules were met.

Since the inside of this building has no visually damaged or friable ACBM no assessment is necessary and we recommend all non-friable material be maintained under an operation and maintenance program.

There may be ACBM located behind walls, above ceilings, or in areas that are not accessible to use. If ACBM is present in these areas, the condition of it is unknown and this should be a consideration before any remodeling or demolition is started.