

**THREE YEAR RE-INSPECTION
2010**

**DESIGNATED PERSON INFORMATION AND REINSPECTION
APPROVAL**

Designated Person:

**Mark Chrusciel
Manager of Maintenance
GRAND RAPIDS PUBLIC SCHOOLS
900 Union Street, NE
Grand Rapids MI 49503**

Telephone Number: (616) 819-3010

North Park Elementary School
3375 Cheney Ave NE

Building Name

This statement certifies that the three year re-inspection has been conducted by accredited persons and in accordance with the AHERA regulations. I have reviewed the revised plan, the recommended response actions and schedules, and approve for implementation.

**Mark Chrusciel
Manager of Maintenance**



Signature

6-10-10

Date

**THREE YEAR REINSPECTION
2010**

**Name of accredited inspectors and Management Planners
who performed reinspection:**

Name: Bruce Johnson

Signature: Bruce Johnson
State License Number A7552

Name: Richard Natte

Signature: Richard Natte
State License Number A3550

Date: 9-30-10

THREE YEAR RE-INSPECTION 2010

This re-inspection was done in accordance with AHERA Act 763.85, Part B. All known Asbestos Containing and all assumed Asbestos Containing Material listed in the Management Plan was visually inspected to determine if there has been a change in the condition of the material from an undamaged state, to one showing damage.

The visual inspection was performed by Bruce Johnson and Richard Natte on the entire building with the use of the Management Plan, along with the past reinspections and all of the 6 months surveillances, to determine if there has been changes in the physical condition of any ACBM, and to assure that all past response actions and schedules were met.

Since the inside of this building has no friable ACBM (Other than thermal system insulation which may be treated as non-friable as per AHERA 763.85 (c) General), no assessment is necessary and we recommend all known Asbestos Containing and all assumed Asbestos Containing Material be maintained under an operation and maintenance program.

For quick reference, the ASBESTOS LOCATIONS section gives an updated list of all known or assumed ACBM locations found in this building. However, there may be ACBM located behind walls, above ceilings, or in areas that are not accessible. If ACBM is present in these areas, the condition of it is unknown and this should be a consideration before any remodeling or demolition is started.