

**THREE YEAR RE-INSPECTION
2013**

**DESIGNATED PERSON INFORMATION AND REINSPECTION
APPROVAL**

Designated Person:

**Ken Klomparens
Director of Maintenance
GRAND RAPIDS PUBLIC SCHOOLS
900 Union Street, NE
Grand Rapids MI 49503**

Telephone Number: (616) 819-3010

North Park Elem.

3375 Cheney Ave NE

Building Name

This statement certifies that the three year re-inspection has been conducted by accredited persons and in accordance with the AHERA regulations. I have reviewed the revised plan, the recommended response actions and schedules, and approve for implementation.

**Ken Klomparens
Director of Maintenance**

Ken Klomparens
Signature

Date

**THREE YEAR RE-INSPECTION
2013**

***Name of accredited inspectors and Management Planners
who performed reinspection:***

Name: Robert TerVeen

Signature: _____

State License Number _____

Name: Thomas Schieffer

Signature: _____

State License Number _____

Date: _____

THREE YEAR RE-INSPECTION 2013

This re-inspection was done in accordance with AHERA Act 763.85, Part B. All known Asbestos Containing and all assumed Asbestos Containing Material listed in the Management Plan was visually inspected to determine if there has been a change in the condition of the material from an undamaged state, to one showing damage.

The visual inspection was performed by Robert TerVeen & Thomas Schieffer on the entire building with the use of the Management Plan, along with the past reinspections and all of the 6 months surveillances, to determine if there has been changes in the physical condition of any ACBM, and to assure that all past response actions and schedules were met.

Since the inside of this building has no friable ACBM (Other than thermal system insulation which may be treated as non-friable as per AHERA 763.85 (c) General), no assessment is necessary and we recommend all known Asbestos Containing and all assumed Asbestos Containing Material be maintained under an operation and maintenance program.

For quick reference, the ASBESTOS LOCATIONS section gives an updated list of all known or assumed ACBM locations found in this building. However, there may be ACBM located behind walls, above ceilings, or in areas that are not accessible. If ACBM is present in these areas, the condition of it is unknown and this should be a consideration before any remodeling or demolition is started.